

## Product Change Notice

Date:	June 12, 2023
Overview:	Labeling change for select parts, moving from rotor stamping to adhesive labels on the cable
Reason for Change:	Consistency – We have been phasing out the rotor stamping and moving toward adhesive labels which offer higher process reliability and traceability
Affected Part No(s):	Please see part number listing on page 3 of this PCN
Design Change Detail:	We are moving from stamping the product information on the rotor to putting adhesive labels on the cable
Effective Date:	Running change beginning immediately
Last Time Buy Deadline:	N/A
Pricing:	No change
ebm-papst employee:	Jeannine Zenobi
Attachments:	Sample labels and listing of affected part numbers (detailed on pages 2 and 3 of this PCN, respectively)
Comments:	This change does not affect the form / fit / function of the product

### Old Version – Stamped label on rotor

<b>ebmpapst</b> M2D068-BF04-04
220/380V~ 50Hz 29W 0,12A
2400min <sup>-1</sup> Ins.Cl.F TOP-out
Made in Germany

### New Version - Adhesive label on cable

(This example shows a different part number than above)

The adhesive label measures 108x25 mm and will be attached to the cable.

The stamped label on the rotor will be removed.



**Affected Part Numbers**

M2D068-DF02-12	M4E068-DF01-05
M2E068-BF07-01	M4E068-DF01-50
M2E068-CF01-60	M4E068-DF01-85
M2E068-DF05-01	M4E068-DF01-91
M2E068-DF05-14	M4E068-DF01-92
M2E068-DF05-79	M4E068-DF47-86
M2E068-DF05-B8	M4E068-EC01-40
M2E068-DF13-79	M4E068-EC01-53
M2E068-EC01-01	M4E068-EC01-54
M2E068-EC01-22	M6E068-DF04-06
M2E068-EC07-18	R2E133-AX01-09
M4E068-CF01-01	R2E146-BF32-15
M4E068-DF01-01	R2E146-BF32-16

Form No: 1274	Quality Record - No	Page 1 of 1
Rev. – Orig, Released 08/28/14	Retention Period – 1 year	Dept. Owner – Sales/Marketing