

PICkitS.dll Revision History

Version	Date	By	Description
1.3	12-19-06	MM	<ul style="list-style-type: none"> Original Release
1.5	6-27-07	MM	<ul style="list-style-type: none"> Added LIN, Microwire, I2C Slave protocols Added End Of Script tags to verify script completion Added universal timeout for scripts Fixed bug that inserted data in the Transactions window wherever the cursor was located. All new data is tagged on the end now Added protocol specific classes and extensive function calls for PKSA configuration and ease of use for custom applications
1.6	7-10-07	MM	<ul style="list-style-type: none"> Fixed error that sometimes showed a completed script as timed out
1.7	8-14-07	MM	<ul style="list-style-type: none"> Fixed error that did not clear read buffer during USART reads.
1.8	10-10-07	MM	<ul style="list-style-type: none"> Added functions Device.Get_Buffer_Flush_Time and Device.Set_Buffer_Flush_Time
1.9	12-05-07	MM	<ul style="list-style-type: none"> Added function Device.Clear_Comm_Errors Added functions Device.Get/Set_Buffer_Flush_Parameters Added function I2CM.Write_Using_PEC Added class mTouchCap
2.0	7-02-08	MM	<ul style="list-style-type: none"> Added LIN slave functionality Improved LIN response time Added class mTouch2
2.1	8-18-08	MM	<ul style="list-style-type: none"> Added SPI Send_And_Receive_Data command Overloaded I2CM Read and Write to include two byte addressing
2.2	1-30-09	MM	<ul style="list-style-type: none"> Added special mTouch I2C command ReadDevToolData Now compatible with 64 bit Vista Added functions in class Device to read PKSA firmware version and the DLL version Added class Firmware to facilitate firmware updates of PKSA and LIN devices Added LIN function so PKSA GUI does not get 'stuck' in LIN mode
2.4	3-11-09	MM	<ul style="list-style-type: none"> Added mTouchLV class Fixed logic error in USART.Set_Baud_Rate – was not updating the control block