



18-May-2023

PCN #: PCN-23-171053

Subject : 35 position AMPSEAL Wire Seal

Description of Change : Please be aware of an upcoming feature and material change to the following part numbers

776164-1

776164-2

776164-4

776164-5

776164-6

The material change is to one of the components that makes up to the final material

The feature change is to the ribs in the circuit holes and the sealing ribs on perimeter of the seal

Reason : The material is being changed because one of the components used in the final material was no longer available. The seal vendor performed validation testing before seals were molded and sent for testing

The geometry change was to update the circuit geometry to the latest design used by the vendor and to change the design of the ribs on the perimeter of the seal to compression ribs

Key Dates :

Contact By Date:02-Oct-2023

Implementation Date:02-Oct-2023

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
776164-4			
776164-6			
776164-5			
776164-1			
776164-2			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.