

« Accessories

Fluke i1010 AC/DC Current Clamp

Highly reliable, measures 1 A to 1000 A and provides accurate current reading without breaking the circuit. Buy Online Now.

[Check Pricing/Buy Now](#)

Manuals



Overview

[Reviews](#)

[Specs](#)

[Models](#)

[Accessories](#)

[Resources](#)

Fluke current clamps extend the current ranges of Fluke tools. The Fluke i1010 AC/DC current clamp is highly reliable, measures 1 A to 1000 A and provides accurate current reading without breaking the circuit. This clamp measures both ac and dc current with a large jaw, battery-powered Hall-effect probe that gives access to difficult to reach areas. Compatible with most Fluke multimeters.

Product Registration

Products

- [Buy Fluke Accessories](#)
- [Buy Factory Reconditioned](#)
- [Contests and Promotions](#)
- [Manuals](#)
- [New From Fluke](#)
- [Product Registration](#)
- [Test Tools Catalog](#)
- [Where to Buy](#)

Company

- [About Us](#)
- [Awards](#)
- [Careers](#)
- [Companies](#)
- [Integrity](#)
- [Press](#)
- [Supplier Handbook](#)
- [Tax Information](#)

Customer Service

- [Contact Us](#)
- [Directions](#)
- [Feedback](#)
- [Safety Notices](#)

[Fluke Newsletters Signup](#)



United States / English

- [Safety Notices](#)
- [Site Map](#)
- [Privacy Policy](#)
- [Fluke Terms of Use](#)
- [Fluke Terms & Conditions of Sale](#)
- Copyright ©1995-2015 Fluke Inc.

[Back to top of page](#)