

Product Change Notification

PCN Date:	Dec 30, 2022		
Supplier Name:	Pulse Electronics		
Pulse PCN No.	PCN 22-032		
Description of Change	Add 2 drop of epoxy to bond coil and header		
Reason for Change	Prevent coil drop and impact coplanarity		
	Present		New
	No epoxy to fix coil and h	eader	Add epoxy to fix coil and header
Summary of Changes	点 epoxy 位 置		位.
Traceability guidelines	By date code, traceability record can be provided upon request		
Qualification Data	P0421NL add epoxy reliability t		
Customer Part Number	Pulse Part Number		PCN Effectivity Date
1	P0421NL		2/1/2023
/	P0421NLT		2/1/2023

Customer: Generic
Originator: David Lin